


STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1/94 To (mo./yr.) 1/95
2. DOGM File Number (Mine No): M 021 / 004
3. Mine Name: Escalante Silver Mine
4. Mineral(s) Mined (or permitted to mine): None - Mine Closed
5. Type of mine ☐ Surface Mine or ☒ Underground Mine
6. Legal Description (Location of Lands Affected):
1/4, SE 1/4, Section 2, Township 36S, Range 17W
1/4, 1/4, Section , Township , Range
1/4, 1/4, Section , Township , Range
7. Name of Operator or Company: Hecla Mining Company
8. Permanent Street Address : 6500 Mineral Drive
City, State, Zip: Coeur d'Alene ID 83814
Phone: (208) 769-4100
9. Company Representative (or designated operator):
Name: Alan Wilson
Title: Senior Reclamation Engineer
Business Address: 6500 Mineral Drive
City, State, Zip: Coeur d'Alene ID 83814
Phone: (208) 769-4100

☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☐ No ☒
2. If active, how much ore or mineral was mined? _____

3. How much additional acreage was disturbed during the past year? None
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.
- _____
- _____
- _____
5. How much acreage was reclaimed during the past year? 75
6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
- The tailings pond was capped and a diversion ditch installed
around the perimeter of the pond. The access road to the
tailings pond was also reclaimed. Seeding has not been
completed.
7. What is the total disturbed acreage at years end? 30
8. Briefly summarize any mining and/or reclamation plans for the upcoming year.
- Seeding all areas reclaimed in 1994
- _____
- _____
- _____

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

ALAN WILSON

Title of Operator:

SENIOR RECLAMATION ENGINEER

Signature of Operator:


Alan Wilson

Date:

1/6/94

71/021/004

sw



January 6, 1995

Mr. D. Wayne Hedberg
Department of Natural Resources
Division of Oil, Gas, and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, UT 84180-1203

Dear Mr. Hedberg:

Enclosed please find the 1994 Annual Report for our Escalante Mine. We are going to try to get the seed in as soon as the ground thaws and dries out enough to get equipment on. I'll let you know as soon as we decide to do it.

Sincerely yours,

A handwritten signature in cursive script that reads "Alan Wilson".

Alan Wilson
Senior Reclamation Engineer